



## Restoration of the Mariinsky hospital cast iron fence

Materials supplier: Mendeleev Ltd.

Object address: 56, Liteyny Prospekt.

Date of operation: June, 2011.

Air temperature: +18°C.

Relative air humidity: 75%.

Pic.1 – The Mariinsky hospital with an iron cast fence

In 1803-1805 in honor of the city's centenary at the expense of empress Maria Feodorovna a hospital for the poor was built, the Mariinsky hospital. The central building and the side wings face Liteyny Prospekt. The project author is D. Quarenghi. The front yard is separated from the street by an iron cast fence. From time to time the fence was repainted, its original refinement being lost. The issue of architectural monuments (buildings facades, sculptures, metallic constructions) preservation is extremely topical today. Architectural constructions restoration is a difficult and complex type of construction works. Quality restoration requires profound and special experience and skills and is justly considered the highest level of construction mastery. The specialists of MATIS company have been engaged in restoration of metal decor and metal parts at the objects of federal and municipal preservation for several years and, therefore, possess the adequate experience in different buildings facade restoration. In May, 2011 MATIS company commenced the cast iron fence restoration works. To remove the multilayer paint coating Old Paint Remover SP-67, grade A was used.

Pic.2 – Old Paint Remover SP-67, grade A with the fence cleaned from paint on the background.

Old Paint Remover SP-67, grade A works efficiently on vertical, horizontal and ceiling surfaces.

Pic.3 – Application of Old Paint Remover SP-67, grade A with a brush.

Old Paint Remover SP-67, grade A contains neither acids nor alkalis, and thus, does not corrode the metallic surfaces being cleaned. The agent is applied with consumption of minimum 300 ml per square meter.

Pic.4 – Old Paint Remover SP-67, grade A was applied onto the decorative elements.

Pic.5 – Composition exposure time is 30 minutes, consumption rate 350 ml per square meter.

Pic.6 – The works execution procedure was violated

Please note that the remover was applied unevenly. The agent must be applied with a brush, a spattle or a roller in even layers without tintage.

Pic.7 – Old Paint Remover SP-67, grade A made the paint blister

Exposure time varies from 30 to 50 minutes. The softened paint layers are removed with a spittle or a wire brush. It is more convenient to flush the disrupted paint layer and the worked-out Old Paint Remover SP-67 grade A with a radial water jet (using Kärcher-type high-pressure cleaner).

Pic.8 – Removing the old paint with a spattle

Pic.9 – Removing the old paint out of the hard-to-reach places with a wire brush

Old Paint Remover SP-67 grade A coped with the task excellently, all the intricate and decorative elements of the cast iron were cleaned down to the metal.

Pic.10 –The fence cleaned from the old paint with Old Paint Remover SP-67, grade A

After the old paint removal the metallic surface must be degreased by solvent to enhance the adhesion of the primer and metal. During metal painting the primer is applied in two or more layers. Then metal is painted. Simultaneously with cast iron fence restoration the limestone plinth is restored.

Pic.11 – Fence elements are coated with a primer

Pic.12 – Applying the second primer layer



## ООО «Менделеев»

Разработка и производство реставрационных и лакокрасочных материалов

Адрес: 191040, Санкт-Петербург, Лиговский проспект, д. 50 корп. 17, вход №2, домофон «1»

Телефоны: (812) 327-44-24, 327-44-25, 327-44-27

Е-mail: mendelev@dmendelev.com

Часы работы: пн-пт 10:00-18:00, обед 14:00-15:00

Сайт: www.dmendelev.com

---

Рис.13- Fence elements already coated with a primer

## The cast iron fence after restoration

Pic.14 – The cast iron fence after restoration with Old Paint Remover SP-67, grade A

Pic.15 – Decorative elements of the fence before restoration

Pic.16 – Decorative elements of the fence after restoration

Pic.17 – The fence and the plinth restored

- metal bars and gates
- hospital for the poor
- decorative fence
- how to remove paint from metal decor
- matis company
- complex restoration of the fence
- mariinsky hospital
- metal fences
- restoration repair of cast iron stairs
- metal parts restoration
- fence restoration
- mariinsky hospital central gate restoration
- old paint removal from decorative elements
- old paint removal from metal
- universal method of fence restoration
- cast iron fence